

HEV Fleet Testing - Maintenance Sheet

2001 – Honda Insight Hybrid



U.S. Department of Energy
**Energy Efficiency
 and Renewable Energy**



Advanced Vehicle Testing Activity

VIN #JHMZE14711T002487

Date	Mileage	Description	Cost
-	-	Vehicle recalled for Powertrain Control Module Software. Dealer indicated changes not applicable to Arizona	warranty
11/16/2001	2,036	Failed on road. Headlights left on by driver. Battery jumped.	warranty
1/22/2002	3,965	Change oil and rotate tires	warranty
3/19/2002	6,950	Reapply paint sealer	warranty
3/25/2002	7,091	Replaced left rear tire after blow out	\$ 81.60
3/28/2002	7,166	Replace left rear ABS sensor damaged in tire failure	\$ 329.44
4/16/2002	8,178	Change oil and rotate tires	\$ 29.71
6/28/2002	12,158	Change oil and rotate tires	\$ 38.41
8/19/2002	13,939	Change oil and rotate tires	\$ 40.45
8/28/2002	14,478	15,000 mile service	\$ 182.14
9/17/2002	15,952	Inner fender liner loose. Replaced left and right strakes and left fender liner.	warranty
1/11/2003	18,670	15,000 mile service	\$ 188.89