

FREEDOMCAR & VEHICLE TECHNOLOGIES PROGRAM

HEV Fleet Testing

Advanced Vehicle Testing Activities

Maintenance Sheet for 2000 – Honda Insight Hybrid



VIN #JHMZE1359YT003672

Date	Mileage	Description	Cost
9/22/2001	11,081	Driver hit parking bumper and damaged front air dam. Air dam replaced	\$ 1,992.02
9/24/2001	12,008	Change oil	\$ 30.12
12/3/2001	20,233	Tires require replacement. Original equipment tires not available locally from Honda or aftermarket.	\$ -
12/3/2001	20,233	Change oil	\$ 29.95
12/26/2001	22,768	Replace front tires. Original equipment tires ordered by Discount Tire Company	\$ 141.59
1/26/2002	27,426	Change oil	\$ 21.97
5/4/2002	32,853	Change oil	\$ 35.96
6/7/2002	44,130	Four wheel brake service	\$ 177.78
8/20/2002	53,249	Replace 12 volt accessory battery	\$ 70.00
11/15/2002	58,228	60,000 mile service and replace 2 tires	\$ 830.48
8/7/2003	70,748	6 months 7500 mile service	\$ 239.41
8/19/2003	71,901	Traction battery pack and battery control module replaced	warranty
9/5/2003	71,901	Rear view detached. Mirror replaced	\$ 113.80
10/22/2003	72,210	PCM software updated	warranty
2/12/2004	73,673	75,000 miles service	\$ 253.28



U.S. Department of Energy
Energy Efficiency and Renewable Energy

Bringing you a prosperous future where energy is clean, abundant, reliable, and affordable