

HEV Fleet Testing - Maintenance Sheet 2002 – Toyota Prius Hybrid



U.S. Department of Energy
**Energy Efficiency
and Renewable Energy**



Advanced Vehicle Testing Activity

VIN #JT2BK18U520038836

Date	Mileage	Description	Cost
8-Aug	11,142	Oil change	\$ 35.44
11-Oct	14,133	Rear Bumper damaged in collision (not included in maintenance costs)	\$ 528.85
01/02/03	15,650	15,000 miles service	\$ 166.56
8/5/2003	25,463	Steering erratic. Rack and pinion replaced (occurred after the completion of formal testing & reporting)	warranty
1/26/2004	30,000	30,000 mile service. Oil over filled at 30,000 mile service.	\$ 166.56
		Over fill caused error code resulting in vehicle quit on road.	warranty
2/13/2003	32,500	Steering erratic. Rack and pinion replaced	warranty