

## EREV Fleet Testing

### Advanced Vehicle Testing Activity

### Maintenance and Repair History for 2011 Chevrolet Volt

VIN# 1G1RD6E48BU100815

| Date       | Mileage | Description   | Cost     |
|------------|---------|---|----------|
| 4/4/2011   | 831     | Replaced trans mount and mounting bracket- warranty             | N/C      |
| 6/13/2011  | 5,736   | Repaired fuel door  | N/C      |
| 10/4/2011  | 7,538   | Replaced trunk carpet   | N/C      |
| 10/19/2011 | 7,685   | Reprogrammed multiple modules - Software upgrade 11137          | N/C      |
| 4/4/2012   | 8,200   | Replaced hybrid battery bracket                                 | N/C      |
| 4/4/2012   | 8,200   | Replaced 120 volt charge cord                                   | N/C      |
| 8/8/2012   | 17,160  | Changed oil and filter and rotated tires                        | \$64.87  |
| 9/6/2012   | 20,500  | Replaced and balanced one tire                                  | \$188.62 |
| 4/23/2013  | 30,067  | 30K mile service  | \$160.96 |
| 5/8/2013   | 31,874  | Checked air bag system - poor connection                        | N/C      |
| 7/15/2013  | 37,333  | Replaced 12V battery, surge tank sensor and reprogrammed module | N/C      |
| 7/31/2013  | 38,487  | Changed oil and filter - under warranty                         | N/C      |
| 10/25/2013 | 46,125  | Replaced and balanced two tires                                 | \$299.42 |
| 12/11/2013 | 50,484  | Changed oil and filter  | \$63.20  |
| 3/19/2014  | 60,015  | 60K mile service  | \$167.81 |
| 8/13/2014  | 67,837  | Replaced engine mount, changed oil and filter                   | \$292.79 |
| 9/8/2014   | 70,270  | Replaced left front window regulator                            | \$50.00  |
| 2/20/2015  | 83,626  | Changed oil and filter and rotated tires                        | \$69.99  |
| 4/2/2015   | 87,222  | Replaced 12v battery  | \$257.13 |
| 5/15/2015  | 91,525  | Replaced window regulator due to window falling off track       | \$171.44 |
| 6/15/2015  | 96,756  | Changed oil and filter and rotated tires                        | \$69.99  |
| 6/16/2015  | 96,759  | Replaced and balanced two tires                                 | \$391.56 |
| 7/30/2015  | 101,970 | Recall 13202: Reprogrammed T6 power invert module               | N/C      |

## Advanced Vehicle Testing Activity

|            |         |  |           |
|------------|---------|--|-----------|
| 7/30/2015  | 101,970 | Recall 14274: Replaced both liftgate struts                                      | N/C       |
| 7/30/2015  | 101,970 | Recall 14617: Reprogrammed and setup BCM   | N/C       |
| 7/30/2015  | 101,970 | Recall 14522: Replaced Evap line and canister                                    | N/C       |
| 7/30/2015  | 101,970 | Replaced low side service port core and recharged system due to refrigerent leak | \$283.00  |
| 9/29/2015  | 105,989 | Changed oil and filter and replaced low beam bulb and wiper blades               | \$126.74  |
| 12/31/2015 | 107,632 | Replaced right headlight   | \$22.14   |
| 4/12/2016  | 117,232 | Replaced left front wheel speed sensor, hub bearing, water pump, and belt        | \$1696.99 |
| 4/18/2016  | 117,327 | Replaced radiator hose, filled and bled cooling system                           | \$485.79  |