

## HEV Fleet Testing

### Advanced Vehicle Testing Activity

### Maintenance and Repair History for 2013 Chevrolet Malibu Eco

VIN# 1G11D5RRXDF106605

Date	Mileage	Description	Cost
2/11/2013	4,365	Replaced battery cooling fan - under warranty	N/C
3/25/2013	8,487	Changed oil - under warranty	N/C
3/26/2013	8,684	Rotated tires	\$15.00
3/28/2013	9,032	Inspected generator control module - Recall #12238	N/C
6/25/2013	23,533	Changed oil - under warranty	N/C
6/25/2013	23,533	Replaced generator control module - Recall #13136	N/C
8/2/2013	30,142	30K mile service	\$155.99
10/4/2013	40,665	Changed oil and rotated tires	\$55.99
1/13/2014	58,007	Changed oil and filter and rotated tires	\$59.99
1/27/2014	60,064	60K mile service	\$161.57
7/22/2014	70,056	Replaced and balanced one tire	\$229.88
8/19/2014	72,448	Changed oil and filter	\$59.99
9/26/2014	83,317	Changed oil and filter	\$59.99
11/3/2014	90,941	Changed oil and filter and replaced and balanced one tire	\$284.54
11/6/2014	90,941	Vehicle would not start. Towed to shop and diagnosed weak 12V battery.	\$66.50
11/14/2014	92,740	Vehicle would not start. Towed to dealership and replaced 12V battery.	\$260.66
11/21/2014	92,812	Replaced blower motor	\$263.01
12/15/2014	96,791	Replaced driver side headlight	\$25.00
1/7/2015	96,828	97,500 mile service	\$313.28
2/25/2015	99,003	Replaced gas cap to clear "check engine" light	\$33.19
5/5/2015	109,214	110K mile service	\$339.89
7/2/2015	120,322	Changed oil and filter	\$59.99
7/7/2015	120,328	Recall #14772 - BCM reprogrammed	N/C

## Advanced Vehicle Testing Activity

7/7/2015	120,328	Repaired ignition key - key broke off in ignition	\$92.99
7/15/2015	122,538	Replaced left headlight bulb	\$34.54
8/31/2015	126,095	Flushed A/C system, replaced compressor and drier element, and recharged due to A/C blowing warm air	\$1122.35
9/23/2015	128,450	Changed oil and filter and fixed driver side door panel	\$96.81
9/24/2015	128,458	Re-sealed oil pan, replaced front cover gasket and crank seal, and added oil due to oil leak	\$999.24
10/5/2015	129,655	Replaced driver side headlight	\$25.00
10/8/2015	131,006	Replaced 12v battery	\$242.48
10/12/2015	131,018	Replaced windshield wiper	\$18.11
3/4/2016	144,138	Changed oil and filter and rotated tires	\$69.99
7/5/2016	151,603	150K mile service	\$445.91
7/27/2016	154,990	Replaced two tires	\$308.04
9/8/2016	159,700	Replaced left front low beam bulb	\$11.95