



HEV Fleet Testing

Advanced Vehicle Testing Activities

Maintenance Sheet for 2005 Ford Escape 4WD

VIN # 1FMCU96H15KE18237

| Date | Mileage | Description | Cost |
|------------|---------|---|------------|
| 6/7/2005 | 5,074 | Changed oil using synthetic 5W20 | \$65.43 |
| 7/6/2005 | 10,349 | Changed oil and rotated tires | \$43.96 |
| 7/28/2005 | 16,681 | Changed oil | \$27.95 |
| 8/23/2005 | 21,937 | 15K service | \$361.49 |
| 9/15/2005 | 26,894 | Changed oil and rotated tires | \$28.44 |
| 9/29/2005 | 29,329 | Replaced windshield | \$213.20 |
| 10/18/2005 | 32,123 | 30K service and replaced AC filter and synthetic gear oil | \$644.44 |
| 11/17/2005 | 37,119 | Preventative maintenance | \$28.44 |
| 1/9/2006 | 46,267 | 45K service | \$386.04 |
| 2/27/2006 | 55,266 | Changed oil and rotated tires | \$29.99 |
| 4/4/2006 | 61,195 | 60K service | \$274.29 |
| 4/4/2006 | 61,195 | Replaced rear left control arm, shield, and alignment | \$461.19 |
| 5/9/2006 | 67,473 | Changed oil | \$30.28 |
| 6/28/2006 | 77,872 | Ford maintenance - oil change, tire rotation, filters, lube and battery service | \$174.63 |
| 7/24/2006 | 81,216 | Resecured fuel bank - strap came loose causing rear noise | NC |
| 8/10/2006 | 84,016 | Changed oil | \$43.07 |
| 9/1/2006 | 89,208 | Replaced windshield | \$209.31 |
| 9/6/2006 | 90,049 | Changed oil; rotated tires; inspected brakes, air filters, hoses, and belts; and flushed cooling system | \$162.97 |
| 10/10/2006 | 95,252 | Changed oil | \$35.90 |
| 11/22/2006 | 105,651 | Changed oil | \$41.42 |
| 12/7/2006 | 110,509 | Changed oil | \$42.36 |
| 1/10/2007 | 120,287 | 120K Service | \$143.81 |
| 2/8/2007 | 128,348 | Changed oil and replaced gas cap | \$68.33 |
| 3/7/2007 | 129,000 | Replaced and calibrated PCM | \$1,438.71 |
| 5/2/2007 | 134,246 | Replaced water pump and air filter | \$692.18 |
| 5/21/2007 | 134,970 | Changed oil | \$42.74 |
| 6/26/2007 | 145,441 | Changed oil | \$42.14 |

| Date | Mileage | Description | Cost |
|-------------|----------------|--|-------------|
| 8/15/2007 | 147,742 | Towed to dealership (would not start) - cables shorted to ground | \$580.77 |
| 9/11/2007 | 149,486 | No start (possible recall issue), service harness installed, and performed recall work | NC |
| 9/24/2007 | 149,590 | Towed to dealership (vehicle stalling after being driven for 30 miles) - issue corrected from recall | NC |
| 9/24/2007 | 149,598 | Changed oil and replaced air filter, radiator hose, and alternator drive belt | \$273.39 |
| 11/13/2007 | 154,626 | Replaced and balanced two tires | \$168.53 |
| 11/13/2007 | 154,626 | Changed oil | \$43.01 |

