FREEDOMCAR & VEHICLE TECHNOLOGIES PROGRAM

HEV Fleet Testing

Advanced Vehicle Testing Activities Maintenance Sheet for 2002 – Toyota Prius Hybrid



VIN #JT2BK12U920038976

Date	Mileage Description	Cost
3/22/2002	7,607 Changed oil, rotated tires	\$27.00
5/9/2002	15,309 Changed oil, rotated tires	\$27.00
6/25/2002	22,523 Changed oil, rotated tires	\$27.00
7/8/2002	24,057 Replace 2 tires out of service	\$127.32
7/29/2002	27,950 Changed oil, rotated tires	\$27.62
8/21/2002	31,897 Check Engine Light on, dealer found an open circuit and broken wire due to manufacturer defect in wire harness of vacuum	NC
9/3/2002	33,432 Changed oil, rotated tires	\$29.00
9/30/2002	38,777 Changed oil, rotated tires	\$29.00
10/17/2002	40,769 Rear Hub and bearing replaced because deteriorated	\$321.26
11/1/2002	43,592 Changed oil, rotated tires	\$29.11
11/17/2002	44,726 Broken wire check engine light	\$-
12/16/2002	51,087 Changed oil, rotated tires	\$30.99
3/17/2003	66,958 Changed oil, rotated tires	\$30.34
4/25/2003	74,980 Changed oil, rotated tires	\$30.67
5/28/2003	80,088 Changed oil, rotated tires	\$30.50
7/7/2003	85,321 Changed oil, rotated tires	\$30.31
7/15/2003	86,263 Check light diagnostic after all light on the dashboard came on	\$85.00

FREEDOMCAR & VEHICLE TECHNOLOGIES PROGRAM

8/5/2003	88,466 Changed one tire	\$63.19
8/19/2003	90,775 90K service	\$392.52
11/4/2003	103,228 Changed oil, rotated tires	\$24.71
12/9/2003	108,429 Changed oil, rotated tires	\$26.23
1/30/2004	115,895 30K service	\$390.30
3/26/2004	122,889 Repaired body damage	\$1,079.01
3/30/2004	123,403 Changed oil, rotated tires	\$35.66
4/29/2004	127,430 ECM replacement for failure	\$1,217.70
5/6/2004	128,152 Changed oil, rotated tires	\$28.15
6/2/2004	133,133 Changed oil, rotated tires	\$28.26
6/30/2004	138,241 Changed oil, rotated tires, and computerized alignment	\$80.47
7/28/2004	142,026 Replaced two tires - under warranty	\$37.57
8/9/2004	143,444 Changed oil, rotated tires	\$32.42
8/24/2004	145,434 Changed oil, replaced two tires	\$76.87
8/27/2004	145,594 Replaced power steering ECM for failure	\$699.08
9/2/2004	145,602 Replaced water pump	\$460.83
9/24/2004	148,291 30K service - Replaced drive belt	\$508.44
10/25/2004	153,462 Changed oil, rotated tires	\$22.19
1/10/2005	160,000 Cleaned and resealed battery pack	warranty