

EREV Fleet Testing

Advanced Vehicle Testing Activity

Maintenance and Repair History for 2016 Chevrolet Volt

VIN# 1G1RC6S52GU114913

Date	Mileage	Description	Cost
2/9/2016	946	Replaced EGR cooler temperature sensor	N/C
2/9/2016	946	Recall 28340 - Reprogrammed engine control module with SPS	N/C
9/1/2016	30,626	30K mile service	\$222.14
9/30/2016	35,441	Remounted fuse block cover and replaced blown fuse	N/C
9/30/2016	35,441	Recall 38240 - Fix manual front seat track lockset pin, 27660 - program PIM, 32340 - ECM reprogramming with SPS	N/C