

BEV Fleet Testing

Advanced Vehicle Testing Activity

Maintenance and Repair History for 2014 BMW i3 EV

VIN# WBY1Z2C59EV285626

Date	Mileage	Description	Cost
6/19/2015	4,472	Replaced A/C compressor - under warranty	N/C