

## ***BEV Fleet Testing***

### ***Advanced Vehicle Testing Activity***

#### ***Maintenance and Repair History for 2014 Smart Electric Drive Coupe***

VIN# WMEEJ9AA5EK732457

<b>Date</b>	<b>Mileage</b>	<b>Description</b>	<b>Cost</b>
11/16/2015	8,722	Replaced blower motor regulator	N/C
7/15/2016	12,402	Replaced right side axel seal due to leak	N/C