

ICE Fleet Testing

Advanced Vehicle Testing Activity

Maintenance and Repair History for 2013 Volkswagen Jetta TDI

VIN# 3VWLL7AJ5DM206371

Date	Mileage	Description	Cost
12/10/2012	4,291	Replaced brake line - under warranty	N/C
3/25/2013	10,035	10K mile service - under warranty	N/C
6/5/2013	20,017	20K mile service - under warranty	N/C
8/1/2013	30,010	30K mile service - under warranty	N/C
6/10/2014	35,263	Replaced loose wiper arm on windshield wipers	\$50.00
6/20/2014	36,725	Replaced A/C compressor under warranty. Charged for towing and labor.	\$112.00
7/23/2014	41,891	Changed oil and filter	\$79.95
8/13/2014	44,756	Repaired left rear tire	\$20.00
8/19/2014	46,036	All warning lights on, checked - found nothing. Cleared warning lights.	\$25.00
9/16/2014	52,141	Changed oil and filter	\$79.95
11/10/2014	61,965	Changed oil and filter	\$79.95
12/4/2014	64,758	Towed for jumpstart	\$104.00
12/19/2014	64,765	Towed to dealership. Dealership performed a diesel fuel system rebuild - under warranty	\$120.00
1/14/2015	70,043	Towed and replaced 12V battery	\$224.37
1/20/2015	70,295	Replaced one headlight	\$56.27
1/28/2015	71,894	Changed oil and filter, serviced transmission, and replaced and balanced one tire	\$708.06
1/29/2015	72,162	Replaced one headlight	\$25.00
3/26/2015	80,004	Replaced fuel pump due to leak. Replaced power steering charge pipe due to leak.	\$617.08
7/2/2015	92,567	90K mile service	\$259.59
7/15/2015	94,247	Evac and recharge A/C - still blows warm air	\$80.00
7/15/2015	94,251	Rebuilt A/C system due to metal shavings found inside	\$1500.00
7/15/2015	94,251	OEM Recall C42G8 - Installed inlays to both rear axle trailing arms	N/C
8/19/2015	97,519	Replaced diesel particulate filter, EGR filter, and necessary gaskets (due to check engine light) and aligned wheels	\$2150.23

Advanced Vehicle Testing Activity

9/14/2015	102,055	100K mile service	\$186.36
10/1/2015	108,013	Replaced driver side headlight	\$49.45
5/19/2016	122,425	Changed oil and filter, serviced transmission, and charged A/C system	\$534.28