

ICE Fleet Testing

Advanced Vehicle Testing Activity

Maintenance and Repair History for 2014 Chevrolet Cruze Diesel

VIN# 1G1P75SZ7E7281014

Date	Mileage	Description	Cost
12/17/2014	7,299	Changed oil and filter and rotated tires	N/C
5/13/2015	13,988	Changed oil and filter and rotated tires	N/C
7/29/2015	20,785	Replaced SES sensor	N/C
9/18/2015	26,974	Changed oil and filter	\$80.36
1/22/2016	46,041	Changed oil and filter	\$70.24
2/4/2016	48,272	Performed water in fuel drain	\$120.00
2/9/2016	48,381	Replaced fuel filter and housing, flushed lines, and inspection due to water in the fuel	\$859.95
4/28/2016	61,911	Changed oil, air filter and fuel filter and rotated tires	\$268.86
7/9/2016	72,142	Changed oil and filter, rotated tires, replaced fluid tank, and performed 32 point inspection	\$224.89
7/22/2016	73,533	Replaced two worn tires	\$352.17
7/22/2016	73,927	Aligned wheels	\$98.39