

ICE Fleet Testing

Advanced Vehicle Testing Activity

Maintenance and Repair History for 2014 Chevrolet Cruze Diesel

VIN# 1G1P75SZ1E7326917

Date	Mileage	Description	Cost
3/23/2015	21,144	Changed oil and filter and rotated tires	N/C
4/15/2015	24,708	Replaced O2 sensor due to check engine light on - under warranty	N/C
6/17/2015	33,973	Replaced leaking reductant injector (emissions system) - under warranty	N/C
6/17/2015	33,973	Replaced fuel filter	\$258.99
7/17/2015	38,130	Replaced and balanced three tires	\$495.44
7/28/2015	39,860	Changed oil and filter	\$75.66
1/22/2016	62,438	Changed oil and filter	\$77.68
7/6/2016	78,019	Changed oil and filter and rotated tires	\$43.37