

ICE Fleet Testing

Advanced Vehicle Testing Activity

Maintenance and Repair History for 2014 Chevrolet Cruze Diesel

VIN# 1G1P75SZ0E7418875

Date	Mileage	Description	Cost
3/26/2015	22,481	Changed oil and filter and rotated tires	N/C
6/12/2015	30,045	Changed oil and filter and rotated tires	\$119.48
9/25/2015	43,788	Changed oil and filter and rotated tires	\$106.43
11/9/2015	50,967	Changed oil and filter	\$85.11
11/9/2015	50,967	Replaced wiper blades and washer fluid	\$59.97
12/23/2015	55,715	Replaced four tires	\$346.39
1/21/2016	58,432	Changed oil and filter and rotated tires	\$156.62
2/8/2016	59,890	Flushed transmission	\$431.75
7/7/2016	75,345	Replaced O2 sensor	N/C
8/3/2016	79,306	Changed oil and filter and rotated tires	\$43.37
9/28/2016	86,268	Changed oil and filter, rotated tires, and replaced air filter	\$64.37